

POTENTIAL HAZARDOUS WASTE SITE SITE IDENTIFICATION ("DISCOVERY")		I. IDENTIFICATION	
		01 ST MO	02 SITE NUMBER
II. SITE NAME AND LOCATION			
01 SITE NAME (Legal, common, or descriptive name of site) Mexico FMGP		02 STREET, ROUTE NUMBER, OR SPECIFIC LOCATION IDENTIFIER High Street & S. Western	
03 CITY Mexico	04 ST MO	05 ZIP CODE 65265	06 COUNTY Audrain
07 CO CODE			
08 CONG DIST			
09 DIRECTIONS TO SITE (Starting from nearest public road; enter up to 4 lines of text) From the intersection of U.S. 54 and Clark Street (Business 54), follow Clark Street north into town. At the intersection of Clark and Boulevard, take Boulevard west for about two blocks until you reach S. Western. Follow S. Western north until it intersects with the railroad. The site is located just south of the railroad tracks.			
III. RESPONSIBLE PARTIES			
01 OWNER (If known) Ameren UE		02 STREET (Business, residential, mailing) One Ameren Plaza, 1901 Chouteau Avenue	
03 CITY St. Louis	04 ST MO	05 ZIP CODE 63166	06 TELEPHONE NUMBER (314) 554-2340
07 OPERATOR (If known and different from owner) Ameren UE (local office)		08 STREET (Business, residential, mailing) 1300 W. Liberty	
09 CITY Mexico	10 ST MO	11 ZIP CODE 65265	12 TELEPHONE NUMBER (573) 473-5048
13 TYPE OF OWNERSHIP (Mark one; use "insert" mode) <input type="checkbox"/> A. PRIVATE <input type="checkbox"/> B. FEDERAL (Agency name): _____ <input type="checkbox"/> C. STATE <input type="checkbox"/> D. COUNTY <input type="checkbox"/> E. MUNICIPAL <input checked="" type="checkbox"/> F. OTHER (Specify): <u>Utility company</u> <input type="checkbox"/> G. UNKNOWN			
IV. HOW IDENTIFIED			
01 DATE IDENTIFIED June 4, 1999 (Month/Day/Year)	02 IDENTIFIED BY (Mark all that apply; use "insert" mode) <input type="checkbox"/> A. CITIZEN COMPLAINT <input type="checkbox"/> B. INDUSTRY <input checked="" type="checkbox"/> C. STATE/LOCAL GOVERNMENT <input type="checkbox"/> D. AERIAL RECONNAISSANCE <input type="checkbox"/> E. RCRA INSPECTION <input type="checkbox"/> F. SURFACE IMPOUNDMENT ASSESSMENT <input type="checkbox"/> G. OTHER EPA IDENTIFICATION <input type="checkbox"/> H. OTHER (Specify): _____		
V. SITE CHARACTERIZATION			
01 TYPE OF SITE (Mark all that apply; use "insert" mode) <input type="checkbox"/> A. STORAGE <input type="checkbox"/> B. TREATMENT <input type="checkbox"/> C. DISPOSAL <input type="checkbox"/> D. UNAUTHORIZED DUMPING <input checked="" type="checkbox"/> E. OTHER (Specify): <u>former manufactured gas plant</u>			
02 SUMMARY OF KNOWN PROBLEMS (Provide narrative description; enter up to 6 lines of text) A manufactured gas plant operated at this location from 1885 until at least 1932. Typical process residuals from this type of operation include coal tar, coke, ash, and spent oxides, which may contain hazardous substances. Subsurface sampling data, collected by DNR in December 1999, indicates the presence of carcinogenic compounds such as benzo(a)pyrene at concentrations that exceed the Missouri Department of Health's Any-Use Soil Levels.			
03 SUMMARY OF ALLEGED OR POTENTIAL PROBLEMS (Provide narrative description; enter up to 5 lines of text) DNR personnel have observed areas of stained soil and what may be coal tar residuals at nearby locations, outside of the current Ameren UE property boundaries.			
VI. INFORMATION AVAILABLE FROM			 96881
01 CONTACT Kimberlee Foster	02 OF (Agency/Organization) Missouri Department of Natural Resources		03 TELEPHONE NUMBER 573-751-8629
04 PREPARED BY Julieann Warren	05 AGENCY MDNR	06 ORGANIZATION	07 TELEPHONE NUMBER 573-751-8629
			08 DATE (Month/Day/Year) Jan 6, 2000